



SPEED'S NEWS

SAINT PAUL



54

PRESIDENT	Gary Wirth	DESIGNEE	Floran Sullivan	1971
V-PRES.	George Smythe	LIBRARIAN	Don Moulin	ST. PAUL, MINN.
SEC-TRES	Harry Dahlquist	EDITOR	Gil Leiter	

NOVEMBER MEETING

The November meeting will be held Nov 8 at 7:30 P.M. at Northern Airmotive (nee Mercury) Holman Field, Downtown St. Paul. The program will be presented by Bob Strathy, who has been experimenting with a fiberglass-foam wing.

MID-MONTH MEETING

The midmonth meeting will be held on the third monday this month. We will meet at Jerry Villenderer's Pit's project. Address is 2555 Fernwood, Roseville. Phone 633 70 78. Time will be 7:30 P.M.

NEW OFFICERS

Elections were held at the October meeting for officers for the year 1972.

PRESIDENT Gary Wirth
V-Pres Jack Hickey
SEC-TRES Harry Dahlquist
Board Bill Hart and Roger Gellerman

They will assume office with the January meeting. Lets give them all the help we can.

SHOW AND TELL

Every meeting is a show and tell. Bring along parts of your projects or your latest experiments for everybody to see.

CRASH LOCATOR BEACON

As the law now stands any aircraft certified after Dec 1971 (next month, not in a few years) will be required to carry a crash locator beacon. The FCC will also require a station licence for this at a cost of \$19.00. It is probably too late, but letters to your congressman won't do any harm.

SEMINARS

Included with this issue is a tenative outline and list of seminars planned for this winter.

AIRCRAFT LIST

A list of projects by chapter 54 members is also included. We have tried to make it complete, but apologize to anyone who was inadvertently missed.

Subjects

- A. Sheet metal
 - 1. Materials
 - 2. Forming
 - 3. Heat treating
 - 4. Deburring
 - 5. Riveting
 - 6. Corrosion protection
- B. Dope and Fabric
 - 1. Preparation
 - 2. Covering
 - 3. Finishing
 - 4. Rib stitching
 - 5. Materials
- C. Steel Structures
 - 1. Fabrication of fittings
 - 2. Tubing preparation
 - 3. Welding
 - 4. Corrosion prevention
- D. Wood
 - 1. Wood selection
 - 2. Glues
 - 3. Wood joints
 - 4. Fitting installation
 - 5. Finishing and rot prevention
- E. Engines
 - 1. Tear down and inspection
 - 2. repair
 - 3. Reassembly
 - 4. Baffling and installation

II. General Forum

The forums will consist of general instruction in the above topics with a maximum participation by the attendees. The forums will be held on Saturdays and will include a noon lunch. Any EAA member is eligible to attend. There will be a small fee for each forum to cover the cost of lunch and materials.

III. Chairmans Responsibility

- A. Work up a detailed outline of material to be presented.
- B. Arrange for experts in various areas to instruct in their specialty
- C. Assemble and print material to be handed out.
- D. Arrange for meeting spot.
- E. Arrange for materials and tools.
- F. Determine maximum number of people course can handle.
- G. Arrange for meal.
- H. Handle registration
- I. Determine necessary fee.

PROJECTS UNDER CONSTRUCTION, RESTORATION, OR COMPLETE

CHAPTER 4 OCTOBER 1971

Builder/Owner	RA No	Aircraft	Status
Al Anderson	23049	Midget Mustang	U.C.
Gordon E Rock	50003	Mustang II	U.C.
Graydon L Carlson	22007	Fly Baby	U.C.
Vernon P Clark	44035	BD-IV	U.C.
Harold C. Dahlquist	22079	Flutter-bug	Flying
Thomas E Doherty	10000	Meyers	Flying
Roger Gallerman	50384	Pietenpol	Engine obtained
William Hart	61000	Mustang II	UC
Cal Jansen	21330	Thorpe T-18	U.C.
Stanely Labore	18000	BD-IV	U.C.
Robert G Larson	18000	Midget Mustang	Flying
Donald S Latterell	51620	Folkerlane 40 Champion	U.C. T
Gil Letter	28647	Stits Fly Mate	U.C.
Gus Limbach	6911	Gusty Tailwind	Flying Under repair
Donald Moulin	50306	Fly Baby	U.C.
Larry Salles	21140	BD-IV	U.C.
Floras Sullivan	20000	Thorpe T-18	Flying
James E Ross	60057	Cavalier	U.C.
Gerald Vilendrer	45011	Titte	U.C.
Jim Meyer		Model A T-draft	U.C.
Gary Wirth	24411	Termite Pietenpol	U.C. U.C.
Thomas R Zoller		BD-IV	U.C.
David L Scott	61305	Baby Great Lakes	U.C.
Miles Lefebvre Jack Hickey		Folker Triplane (3/4) Flybaby ZAC	U.C.